




FIELD FEATURE – What Do You See?

Can you spot the early warning signs?

Based on the thermal signature in this image, what might be happening in this field?

Image 1:



SkyScout NDVI Map from June 4th


Consider the time of year and machine data:

- What issue is going on in the bottom right?
- What machine issue could have caused this?



Revealed Field: Late Season Confirmation:

Image 2:



Wavy patterns across the field indicate areas of reduced crop size.

Analysis

Two areas in the field show a wavy pattern where tillage was performed at a different angle. The grower confirmed that a down-pressure issue was present.

Takeaway

SkyScout NDVI maps helped reveal hidden insights. Moving forward, the grower will avoid intersecting tillage or other field operations that could disrupt the seedbed, ensuring good ride quality and allowing down pressure to function as intended.